

Mary's Market Fuel spill 06/06/17

1:35 pm

Started digging for contaminants and moved from first hole on right side of tank. No visual of contaminants and no gasoline odor at 40" deep at 2:11 pm.

2:12 pm

Started new test hole at 2:12 pm. Detection of contaminants or odor of hydrocarbons at 40". Found 2 inch pvc gas line running parallel between gasoline storage tank and gasoline pump.

2:36 pm

Started 3rd test hole running parallel with underground gasoline line to pump. We chased gasoline line 33.8 feet. No breaks in the line were detected from visual inspection.

3:14 pm

We moved to east side of tank to dig test hole 4. No evidence of hydrocarbon contamination was found.

3:25 pm

Continued chasing gas line to gas pump, no contaminants were detected and no odor.

4:20 pm

Moved to front of pump and dug test hole 5. Gas line was charged at 4:24 pm to conduct visual inspection of line for possible leaks.

4:30 pm

No leaks were detected in the line. The site was back filled and we closed out the inspection.

Conclusion:

It was concluded by me (Curtis Monteau), and the backhoe operator (Michael Clark). There was no contamination of hydrocarbons on excavated area of property. We can only assume that it may be an internal or vendor related issue.